OUT58788

23

337

DISTACTORICAN

03

Chice

ADMIN SEC BR

P & DS CSD

PD

PSD-ICB

TID

PAG DIAXX-4

SPAD NSA-LO

DIA-AP

1933 JUN 13

P 132320Z
FM NPIC WASHBC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 7454.

15TH AF (FOR DI). SAC (FOR DIM/GOLDEN TREE/DOCR. DM 4) 2D AF (FOR DI).

- 1. CAMERA B-125 WAS USED IN MISSION 8100 FLOWN ON 11 JUNE 1966.

 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

 1 4 JUN 1966
 - 2. ORIGINAL NEGATIVE:

- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: SLIGHT INBOARD AND OUTBOARD ROLLER CHATTER IS PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME ØØ95.

C. 9L SIDE: A BAND OF FOG, PERPENDICULAR TO THE MAJOR AXIS,
IS PRESENT ON FRAME ØØØØ. THE MAJORITY OF THE POSITION INDICATOR 34,5
LAMPS, NEAR THE DATA CHAMBER, ARE FAINT AND AT TIMES BARELY DETECTABLE. THE VERTICAL DOT POSITION INDICATOR LAMPS ARE BLOOMED.
MINUTE HAIR LIKE OBSTRUCTIONS ARE INSIDE EACH FIDUCIAL. ULTRASONIC SPLICES WERE USED ON THE HEAD AND TAIL IDENTS AND ALSO BETWEEN
FRAMES 1198/1199 AND 1508/1509. ASSOCIATED WITH THE SPLICES MADE
ON FRAMES 299 AND 1509 ARE CREASES AND WRINKLES IN THE FILM, DUE
TO MISALIGNMENT OF THE FILM DURING THE SPLICING PROCEDURE. STATIC

Advance pooy Sanitized

SECRET

TRACES OF FOG ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION.

siade 1 de and **enemalis** derragodin**g end** derragodin**g end** -2-

- D. BOTH SIDES: THE FRAMES ARE CONSECUTIVELY TITLED 0000 THROUGH 1919.
 - E. THERE WERE NO MAJOR PROCESSING OR CAMERA MALFUNCTIONS.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 40 PERCENT OF THE MISSION.

GP-1

SECRET

-- END OF MESSAGE--